



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor


Ted Stewart  
Executive Director

James W. Carter  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

October 11, 1994

TO: Minerals File

FROM: Lynn Kunzler, Reclamation Specialist 

RE: Site Inspection, Utah Division of Parks and Recreation, Garden City Quarry, S/033/0003, Rich County, Utah

Date of Inspection:	October 4, 1994
Time of Inspection:	11:00 am
Conditions:	intermittent rain
Participants:	Lynn Kunzler, DOGM
Purpose of Inspection:	Document site conditions.

No one else was present during the site inspection. This site located about 1/2 mile due west of the junction of Highways 30 and 89 in Garden City, Utah. Two small stockpiles of material (one sand and one rock fragments) were observed on site. Most of the highwall had been backfilled(?)/regraded to an acceptable slope. No evidence that seeding had occurred was evident. A portion of the floor of the pit was crushed stone. Several photos were taken of the site.

Attempts were made to contact Eldon Robinson, Park Manager of Bear Lake State Park before and during the inspection. In discussions with Park employees at the Park, it was indicated that while the marina work was completed (the main purpose for the quarry), they still intended to remove several loads of material for general use in the Park.

cc: Eldon Robinson, Bear Lake State Park  
John Blake, SITLA  
S033003.94a

